

Boeing 737-406, PH-BTG and McDonnell Douglas DC-9-81, SE-DMB

AAIB Bulletin No: 5/97 Ref: EW/C96/11/4 Category: 1.1

Aircraft Type and Registration:	i) Boeing 737-406, PH-BTG ii) McDonnell Douglas DC-9-81, SE-DMB
No & Type of Engines:	i) 2 CFM56-3C1 turbofan engines ii) 2 Pratt & Whitney JT-8D turbofan engines
Year of Manufacture:	i) 1994 ii) 1991
Date & Time (UTC):	12 November 1996 at 1644 hrs
Location:	Lambourne VOR Holding Pattern Near Romford, Essex
Type of Flight:	Public Transport
Persons on Board:	(i) Crew - 8 - Passengers - 69 (ii) Crew - 7 - Passengers - 70
Injuries:	None
Nature of Damage:	None
Commander's Licence:	i) Airline Transport Pilot's Licence (Netherlands) ii) Airline Transport Pilot's Licence (Norway)
Commander's Age:	i) 34 years ii) 51 years
Commander's Flying Experience:	i) 5,880 hours (of which 2,570 were on type) ii) 8,327 hours (of which 337 were on type)
Information Source:	AAIB Field Investigation

The Boeing 737 (B737) and DC-9-81 (MD81) were inbound to London Heathrow from Amsterdam (Netherlands) and Aarhus (Denmark) respectively. The incident occurred while both aircraft were

under the control of the Lambourne (LAM) Sector Control (frequency 121.225 MHz) at the London Air Traffic Control Centre (LATCC), West Drayton. The controller at the time was a trainee on the sector, being supervised by a qualified mentor controller.

The LAM holding facility is based upon the LAM VOR, ground track 267°M inbound with left turns and outbound leg timing of 1 minute up to and including FL140 (maximum speed 220 kt), or 1.5 minutes at FL150 and above (maximum speed 240 kt).

Due to single runway operations, there was extensive holding in progress for Heathrow arrivals and the MD81 had already entered the LAM holding pattern at FL170 when it was transferred to the control of this sector at 1638 hrs. It was instructed to maintain FL170 and was passed an Expected Approach Time (EAT) of 1649 hrs. Two minutes later, at 1640 hrs, the B737 came onto the frequency, routing inbound to LAM descending to FL170. It was instructed to enter the hold at LAM. Meanwhile, the MD81 had been stepped down progressively until, at 1641 hrs, it was instructed to descend to FL140 and to expedite descent. At 1641:45 hrs the MD81 was requested to report reaching FL140, but replied that it was already at that level. Accordingly the controller then cleared the B737 to descend to FL150. At 1641:55 hrs, this instruction was correctly acknowledged by the B737 crew, including the correct cleared flight level 150.

At 1642:07 hrs, the B737 had about 5 nm to run to the LAM VOR and the MD81 was turning back westward inbound to LAM and was 0.6 nm north of the B737. At this time, the B737 was some 1,800 feet above the MD81. From this point, the LATCC radar display data blocks associated with each aircraft (*ie* flight number, destination and altitude data) became overlapped and could not be deciphered by the controller. This is not an unusual occurrence when aircraft are adjacent in holding stacks and did not cause concern to the controller at that stage.

At 1643:18, the B737 reported that it was taking up the hold at LAM. At this time, it was directly overhead the MD81, 700 feet above it. The aircraft then turned left together in the holding pattern. At this stage, the LATCC Short Term Conflict Alert (STCA) system operated indicating that the B737 and the MD81 had lost the required separation. The STCA system indicated the callsigns of the conflicting aircraft to the controller, but not the respective flight levels. The controller therefore requested each aircraft in turn to confirm its Flight Level. The MD81 was questioned first and responded level at FL140. Immediately following this at 1643:30 hrs, the B737 was questioned and replied that it was 'out of FL143'. The aircraft was then informed that its previously cleared level was FL150 and was instructed to climb immediately back to that level as there was traffic immediately below it and to expedite the climb. Both aircraft were in cloud and neither crew saw the other aircraft. At 1644:30 hrs, the B737 reported level at FL150. The minimum permitted vertical separation in the holding stacks is 1,000 feet.

There was no further communication with either aircraft regarding the incident and each was descended further and handed over in the correct sequence to Heathrow Intermediate Director (North East) Control.

The seriousness of the incident was highlighted when the LATCC Separation Monitoring Function (SMF) data became available a few minutes after the event. The SMF continuously and automatically monitors the separation between transponding aircraft and will detect any breach of pre-defined separation criteria that takes place within the coverage of the LATCC enroute radar system. The SMF is not a collision avoidance system. It provides post event notification to assist in an investigation of the circumstances of the loss of separation. This is produced in a listing, a radar replay simulation and a printed encounter diagram. Once the SMF notification had been received by

the supervisor, the controllers involved then compiled and submitted the appropriate Airprox (C) report about the incident.

The closest distance between the aircraft, derived from recordings of ground based radar facilities, was 100 feet vertically and between 680 and 820 metres horizontally, at 1643:54 to 1643:59 hrs. The B737 had executed a slightly smaller radius turn than the MD81, which resulted in the B737 being slightly ahead and to the left of the MD81 at the time of closest proximity, with both aircraft having left bank applied for the turn, about 25° in the case of the B737.

From the B737 DFDR data, it was determined that the minimum flight level achieved by the aircraft at the time of the incident was 14,052 feet at 1643:46 hrs. (Note: the time base for the B737 DFDR and that for the recorded ground radar facilities were not synchronised). The aircraft was descending at a rate of about 1,000 feet per minute while below FL150, with autopilot and autothrottle engaged. In response to the call from ATC, an immediate climb was initiated using the autopilot and autothrottle systems. The aircraft reached FL150 again at 1644:24 hrs.

Flight Deck Management

The B737 was being operated in accordance with the company's Standard Operating Procedures. The crew had come on duty that day at 0940 hrs in Stockholm. They operated one sector to Amsterdam, arriving at about 1350 hrs. There was a delay of about one hour at the start of the incident sector, with the aircraft becoming airborne from Amsterdam for London Heathrow at 1607 hrs. The First Officer, who had some 2,200 hours on type, was the handling pilot for this sector, with the commander, as non-handling pilot, being responsible for making the ATC radio transmissions and for obtaining updated weather information from the ATIS and VOLMET facilities, as well as contact with the company on the operations frequency for flight progress/ETA purposes and for special messages. Additionally, within the company, the non-handling pilot is normally delegated to make the Passenger Address System (PAS) announcements.

With regard to the altitude/flight level selections on the Mode Control Panel (MCP), whenever the autopilot and autothrottle systems are engaged, it is the responsibility of the handling pilot to select the new cleared level in the MCP altitude window. The selector operates in increments of 100 feet and has a tactile 'click' mechanism for each increment. The new cleared level is required to be confirmed by the non-handling pilot before the change is executed. The non-handling pilot will have acknowledged the new cleared level to ATC. Thus, for normal operations, both pilots have been 'in the loop' and have both confirmed their understanding of the ATC clearance. The aircraft is also equipped with an altitude deviation alerting aural and visual warning system which operates in the event of a deviation away from the altitude set on the MCP.

In this case, at the time of the B737 re-clearance to FL150, the commander (non-handling) was not monitoring the ATC channel because he had deselected it in order to make a PAS announcement to the passengers regarding the holding delay. The clearance readback to ATC was done correctly by the First Officer, but the incorrect FL140 was entered on the MCP. When the commander returned to the monitoring of the ATC channel, he was briefed by the First Officer that the cleared level was FL140. Thus, only one pilot had been involved in the change of cleared flight level process and the two crew cross-checking function did not occur. Therefore, the discrepancy between the cleared level and the MCP selected level went undetected by the crew.

After the event, the B737 crew remained unaware that the situation had resulted from their deviation from ATC clearance as both pilots were convinced that they had been correctly cleared to FL140.

Short Term Conflict Alert (STCA) System

The STCA system is now operational in the majority of UK controlled airspace. The system software is designed to take radar track and altitude data and make linear extrapolations looking forward for a two minute period in order to predict possible conflicts between aircraft pairs when the appropriate separation standards could be lost. In the Terminal Control implementation of STCA, two levels of alert may be issued, dependant upon the predicted proximity of the two aircraft and the time before this occurs. In a 'low severity alert' the aircraft symbols change from green to flashing white and a white pairing line joins the relevant pair on the radar display. A 'list box' also appears, indicating the radar identifications of the pair involved. This alert level may be 'acknowledged' by the controller when resolution instructions have been passed as required. The high level alert causes a colour change to red and this cannot be acknowledged by the controller. The alert remains on until the conflict has been resolved and the appropriate separation regained. The system is designed as a safety net and not a separation assurance tool.

The STCA system uses basic radar data for its calculations, with no 'aircraft intention' input as to altitude clearances issued or the expected initiation of turns (such as over holding fixes). Filters have therefore been built into the software in order to minimise the occurrence of 'nuisance' alerts when separation would be properly maintained, for example, by an aircraft levelling off at a new cleared flight level during a descent.

In this case, after the 'stack linear prediction filter' criteria had been fulfilled, and the 'close to level off delay' mechanism had confirmed the predicted loss of separation for two out of three radar sweep cycles (*ie* about 8 seconds) a low level alert was generated when the vertical separation between the two aircraft had reduced below 900 feet (and about 0.11 nm lateral), then changed to a high level alert when the vertical separation reduced below 600 feet. This alert was generated for a total period of 76 seconds, until the vertical separation again increased above 600 feet. For both alert levels, the Conflict List box gave the two callsigns of the aircraft involved, but not the respective flight levels. These flight levels were also unreadable on the main display because of data block overlap. The alert was triggered some 44 seconds prior to the time of closest proximity. Several seconds were then lost while the controller verified each aircraft's level. Work is currently underway to analyse the effects of garbling on the accuracy of mode C altitude data to determine if it is appropriate to include it in the STCA conflict list boxes.

Traffic Alert and Collision Avoidance System II (TCAS II)

This system, also known as Airborne Collision Avoidance System II (ACAS II), is based upon the use of aircraft transponder equipment to provide warnings of possible collision with other transponding aircraft. The TCAS equipment scans once per second and may detect intruding traffic up to 40 nm distant and within 8,700 feet of the subject aircraft. Traffic movements are assessed and trends are predicted to search for potential conflicts. Advisory alerts will then be triggered when a particular target aircraft becomes a threat, *ie* within a defined volume of airspace around the aircraft. The lower priority alert is a Traffic Advisory (TA) which produces an aural alert '*Traffic, Traffic*' on the flight deck and a visual cue as to the location of the target. For closer encounter predictions where evasive action is required, a Resolution Advisory (RA) is generated which gives both visual and aural cues to the flight crew on the vertical manoeuvre required to avoid a collision. Preventative commands, such as 'do not descend' can also be generated and displayed to the crew where circumstances are such that level flight will maintain safe separation.

Neither aircraft involved in this incident was fitted with such a system, nor was there any current requirement for them to be so equipped. However, the B737 operator indicated that all of its widebody types were already so equipped and that it is currently studying proposals to fit the remaining aircraft in its fleet with the system within the next two years. The MD81 operator indicated that the programme to incorporate TCAS into this fleet would commence in Autumn 1997.

In order to ascertain whether TCAS II would have been effective in this case, the available ground radar data was used in a computer simulation of a TCAS II system by the DERA Malvern. Two simulations were carried out, from the viewpoint of each aircraft involved. The simulation showed the B737 crew would have received a 'Monitor Vertical Speed' RA when descending through FL146. This would have been accompanied by preventative 'Do Not Descend' symbology on the flight instruments (Electronic Attitude Display Indicator (EADI) or Vertical Speed Indicator (VSI), dependant upon the system installation). In addition, the aircraft in close proximity would have been displayed as a colour coded symbol on the Electronic Horizontal Situation Indicator (EHSI), along with the relative height. This RA would have occurred on two occasions while the aircraft were in the turn with less than 600 feet vertical separation. In the case of the MD81, the first RA generated would have been 'Monitor Vertical Speed' accompanied by preventative 'Do Not Climb' symbology, followed by 'Descend, Descend' as the B737 came towards its closest point of approach.

Handling of AIRPROX (C) Reports

An AIRPROX is defined as a situation in which, in the opinion of a pilot or a controller, the distance between aircraft as well as their relative positions and speed have been such that the safety of the aircraft involved was or may have been compromised.

Reports generated by pilots are classified as AIRPROX (P) reports and are considered by the Joint AIRPROX Working Group (JAWG). Reports generated by Air Traffic Controllers are classified as AIRPROX (C) reports and are considered by the Joint AIRPROX Assessment Panel (JAAP).

The JAAP consists of an independent Chairman plus four pilots and four controllers. The panel reviews the reports and assesses the degree of risk inherent in each occurrence. The causal factors are determined and, where appropriate, safety recommendations are made in the interests of flight safety.

Before this incident, a number of Safety Recommendations had been made by JAAP, two of which were in areas relevant to the circumstances of this AIRPROX. These are detailed below:

J95-6' The Panel recommended that the CAA continue the development of ATC radar Short Term Conflict Alert (STCA) devices especially in TMA airspace, including holding patterns.'

The CAA accepted this recommendation and this system is now operative in London, Manchester and Scottish Control Centres.

J95-7 'The panel recommended that the CAA mandate the fitting of TCAS to all commercial air transport aircraft operating in UK controlled airspace as soon as possible.'

The CAA did not accept this recommendation. The CAA policy position acknowledges the proved safety benefits of TCAS and is pursuing the implementation mandate in accordance with ECAC

policy. This policy has proposed the following mandate to apply to all airspace within ECAC member states:

'a. With effect from 1 January 2000, all civil fixed wing turbine-engined aircraft having a maximum take-off mass exceeding 15,000 kg or a maximum approved passenger seating configuration of more than 30 will be equipped with ACAS II, and

b. With effect from 1 January 2005, all civil fixed wing turbine-engined aircraft having a maximum take-off mass exceeding 5,700 kg or a maximum approved passenger seating configuration of more than 19 will be equipped with ACAS II.'

A similar mandate has been proposed by the JAA for aircraft registered in JAA states, using slightly different wording but having the same weight categories and target implementation dates.

CAA Safety Data Department Survey of Flight Level Violations

Results of a CAA safety review of level violations within UK airspace during 1994 indicated an overall total of 235 recorded violations. Of these 165 (70%) were attributed to pilots non-compliance with correctly read-back ATC vertical clearances. Additional analysis of these 'altitude busts' by flight level indicated that the majority of occurrences were at and below FL120 in TMA airspace. It was also found that the majority of deviations were in aircraft from foreign operators (68% of the overall total). Whilst the majority of occurrences occurred during the departure and climb phases, the descent phase also figured prominently as an area of concern.

Safety Recommendations

It was apparent during this investigation that the principal cause of the incident lay in human factors, where the information processing task for the pilot had broken down after a correct read-back of the clearance to ATC. The transient situation of one pilot being 'out of the loop' on the flight deck was undoubtedly instrumental in the error remaining uncorrected until the STCA system warning was triggered and the controller intervened to prevent both aircraft flying at the same level in close proximity, with the attendant risk of collision.

It was also apparent that the addition of accurate altitude data to the STCA Conflict Alert List box display would have been beneficial in reducing the time interval before remedial instructions could be issued by the controller.

It was also apparent that the presentation of the data blocks on the main radar displays could be improved in order to reduce the incidence of data block overlap for adjacent aircraft pairs.

The TCAS II simulation showed that such a system, had it been fitted to either or both aircraft, would have provided timely warning of their mutual proximity.

97-17 It is recommended that KLM review its Standard Operating Procedures to ensure that the monitoring of ATC VHF communications is carried out by two flight deck crew members with the minimum possible interruption during the climb and descent phases of flight. In particular, interruption of monitoring while PAS announcements are made by flight deck crew should be discouraged during these phases.

97-18 It is recommended that the CAA publish guidelines for use by crews receiving and actioning air traffic control clearances, aiming to ensure that safeguards specified by the operator will minimise the risk of non-compliance. Emphasis should be given to the importance, during the climb and descent phases of flight, of not having just one crew member monitoring ATC clearances for longer than is absolutely necessary.

97-19 It is recommended that, where STCA programs are in use, NATS ensures that information is provided in such a way that accurate Mode C data for all aircraft involved is clearly and continuously visible to the controller.

97-20 It is recommended that NATS investigate improvements to radar displays such that controllers are able to see label information in circumstances, particularly in holding stacks, when the labels would normally overlap.

97-21 It is recommended that the CAA make every effort to ensure that the current proposed target dates for the mandatory carriage of TCAS II equipment are implemented by ECAC and by the JAA and that such carriage, and use, is made mandatory within UK airspace.